

EG4

ELECTRONICS

Change Log for 51.2V 100Ah LP4V2 RS485 Firmware Update

Software Version	Change Content	Change Time
Z02T02	Modified to full agreement	05/29/2024
Z02T03	DIP id6 is used to switch the link protocol	06/18/2024
Z02T04	Matches SMk inverters	09/24/2024
Z02T05	Fixed an error where the soc of the Gantwind battery was displayed on the web side of the luxpower inverter when the Gantwind battery was in parallel	01/21/2024
Z02T05	1) Support external display 2) In parallel, the display can view the information of parallel batteries	01/02/2025
Z02T06	1. Fixed the display error issue on the LUX webpage at low temperatures 2. Added SOC99 logic to prevent inconsistencies between SOC and voltage in subsequent operation	01/30/2026

With the release of this document, Z02T06 is the current publicly released firmware. All updates in this changelog are done via RS485 update.